



Access Recreation Group, LLC  
 Cindy Burkhour, MA, CTRS, CPRP  
 2454 Lamplighter Drive, Jenison, MI 49428-9127  
 Mobile (616)560-2378  
[AccessRecreationGroup@juno.com](mailto:AccessRecreationGroup@juno.com)

## Forrest Haven Trail Accessibility Information






**Trail Head Location:**



**Date Assessed:** 6/30/17

### Accessibility Information:

<b>Total Trail Length:</b> .2 miles/elevation change 149'	Overall Barrier Descriptions
<b>Surface:</b> Varied naturally occurring woodland and dune surface, packed dirt, soft sand, meadow grass	mowed meadow grass, cross trail roots, soft sand, decaying wood water bars
<b>Tread Width:</b> Typical = greater than 5' Minimum = less than 12"	narrowed by encroaching vegetation
<b>Running Slope:</b> Typical = 6.7% Maximum = 12.6%	Intermittent steep slope up-hill & down-hill segments
<b>Cross Slope:</b> Typical = less than 2% Maximum = up to 18%	Up to 18% cross slope in straight up/down hill segments with significant soil erosion

\*\* Slopes between 5% & 8.33% are equal to the slope on a ramp in the built environment

Feature Barrier Hill Top Hill Bottom	Elevation	Distance	Average Running Slope %	Photo #	Barrier Description: (slope, cross slope, width, surface, head clearance, reach range, clear space, maneuvering/passing space, operation)
Feature Barrier	585'			1 	Parking: Open gravel parking lot (large crush +1") No accessible parking spaces
Feature Barrier	583'	34'	5.9%	2 	Information Kiosk & Map Box: Moderate slope up-hill route, dirt/grass surface clear space surface is inaccessible grass No accessible route from parking Information posted too high centered at 66" Map box too high at 52"
Feature					Toilets: None
Feature					Potable Water: None
Barrier	596'	272'	4.8%	3 	Easy slope segment Trail width + 5' Packed dirt surface with encroaching vegetation up-hill trail segment cross trail water bar Cross slope up to 18%
Feature Hill Bottom	600'	154'	2.6%	4 	Easy slope segment Trail width + 5' Packed dirt surface changes from gravel to sand over gravel with encroaching vegetation
Barrier	625'	326'	7.7%	5 	Moderate slope segment Trail width + 5' Packed dirt surface with encroaching vegetation  Old log water bar completely across trail tread

Feature Barrier Hill Top Hill Bottom	Elevation	Distance	Average Running Slope %	Photo #	Barrier Description: (slope, cross slope, width, surface, head clearance, reach range, clear space, maneuvering/passing space, operation)
Feature Hill Top	659'	269'	12.6%	<p>6</p>  <p>7</p> 	<p>Very steep slope trail segment up to intersection with intermediate trail loop</p> <p>Trail width + 5'</p> <p>Packed dirt surface with encroaching vegetation</p>